

---

## Silicon Errata and Data Sheet Clarification

---

The MCP9600/01 parts you have received conform functionally to the Device Data Sheet (DS20005426), except for the anomalies described below.

All of the issues listed here will be addressed in future revisions of the MCP9600/01 silicon.

Contact Microchip for the latest silicon fix.

### 1. Module: $T_{H\_ACY}$ , or the $T_H$ Hot-Junction Temperature Accuracy - MCP9600 Only

The Hot-Junction ( $T_H$ ) Temperature Accuracy  $T_{H\_ACY}$  of the MCP9600 devices before Date Code 1723 or Device ID/Revision value of 0x4011, may not meet the specified accuracy in the data sheet, starting from revision C data sheet (DS20005426C) to the latest data sheet. This issue affects the  $T_H$  temperature register only.

The Cold-Junction ( $T_C$ ) and the Junctions Delta ( $T_{\Delta}$ ) Temperature registers are not affected by this issue. These registers meet the accuracy performance as specified in the data sheet.

#### Work around

Convert the  $T_C$  and the  $T_{\Delta}$  temperature data from the units of Degree Celsius ( $^{\circ}\text{C}$ ) to millivolt (mV) using the NIST ITS-90 conversion look-up table or polynomial equation. Then sum the two voltages, and convert the summed value from millivolt to Degree Celsius using the NIST ITS-90 conversion table or polynomial equation.

#### Date Codes that pertain to this issue:

All production devices before Date Code 1723 and with Device ID/Revision register value of 0x4011 are affected, as shown in [Table 1](#).

#### Fix

Devices with Date Code of 1723 or later are not affected. These devices have a Device ID/Revision value of 0x4012.

### 2. Module: Intermittent I<sup>2</sup>C Read Command Clock Stretching Failure - MCP9600 Only

During I<sup>2</sup>C Sequential Read communication for two or more bytes, the MCP9600/L00/RL00 may intermittently fail to Clock Stretch,  $t_{\text{STRETCH}}$ , as described in the data sheet, for bus frequencies greater than 85 kHz (typical). When this failure occurs, the MCP9600/L00/RL00 continues to output the previously transmitted data. For example, when reading the two byte  $T_H$  temperature register, if the device fails to clock stretch for the Least Significant Byte, then the device will output the Most Significant Byte.

#### Work around

Since this issue is intermittent, repeat the Sequential Read instruction until the second byte read is different from the Most Significant Byte.

#### Date Codes that pertain to this issue:

All production devices before Date Code 1845 and with Device ID/Revision register value of 0x4012 or lower are affected, as shown in [Table 1](#).

#### Fix

Devices with Date Code of 1845 or later are not affected. These devices have a Device ID/Revision value of 0x4013.

### 3. Module: Input Range bit (Bit 4 of the Status Register) - MCP9600 Only

When the MCP9600/L00/RL00's Bit 4 of the Status Register, Input Range bit, is set to '1', the  $T_H$ ,  $T_C$  and  $T_A$  registers are not updated as indicated in the Rev E data sheet bit description (DS20005426E). This characteristic may result in what appears to be unpredictable temperature data, if the temperature register is not updated when the thermocouple temperature is near the upper or the lower temperatures limits for the specified thermocouple range. For example, if the thermocouple EMF is within the specified range, but the sum with the Cold Junction EMF exceeds the specified thermocouple range, then the Input Range bit is set to '1' and the temperature registers are not updated.

#### Work around

None.

#### Date Codes that pertain to this issue:

All production devices before Date Code 1845 and with Device ID/Revision register value of 0x4012 or lower are affected, as shown in [Table 1](#).

#### Fix

Devices with Date Code 1845 or later are not affected. These devices have a Device ID/Revision value of 0x4013.

Devices with the Device ID/Revision value of 0x4013 update the temperature registers as follows, when the Bit 4 of the Status Register, Input Range bit, is set to '1':

- If the thermocouple EMF exceeds the specified range, then  $T_H$  and  $T_A$  Registers are not updated, but  $T_C$  Register is updated with a valid temperature data at the specified interval, or  $t_{CONV}$ .
- If the thermocouple EMF is within the specified range, but the sum with the Cold-Junction EMF exceeds the specified range, then  $T_H$  Register is not updated, but  $T_A$  and  $T_C$  Registers are updated with valid temperature data at the specified interval, or  $t_{CONV}$ . The value of  $T_A$  and  $T_C$  Registers can be used to calculate valid Hot-Junction temperature data using the NIST ITS-90 conversion look-up table or polynomial equation.

### 4. Module: Outputs Extra 0x00 data during Sequential Read - MCP9600 Only

When the MCP9600/L00/RL00 Registers are Sequentially Read, the device outputs 0x00 between the Least Significant Byte of the Alert 4 Register and the Most Significant Byte of the Device ID/Revision Register values.

#### Work around

Ignore the byte.

#### Date Codes that pertain to this issue:

All production devices before Date Code 1845 and with Device ID/Revision register value of 0x4012 are affected, as shown in [Table 1](#).

#### Fix

Devices with Date Code 1845 or later are not affected. These devices have a Device ID/Revision value of 0x4013.

### 5. Module: Open Circuit Detection - MCP9601 Only

The MCP9601/L01/RL01 Open Circuit detection Alert feature may not correctly assert. And, if it asserts, then OC Alert output may not remain asserted while the Thermocouple is disconnected; OC Alert output may chatter. This characteristic is primarily due to the minor shift in characteristics of the thermocouple inputs Common-mode typical impedance.

For proper operation, the three external resistors in Figure 1-1 of the data sheet need to be changed from the recommended values in data sheet Revision F (DS20005426F). The following specifications will be changed from the values specified in Revision F of the data sheet  $V_{SiOC}$ ,  $V_{SiNOR}$ , and  $R_A$ ,  $R_B$ , and  $R_C$  from Figure 1-1.

#### Work around

None.

#### Date Codes that pertain to this issue:

All production devices before Date Code 2107 and with Device ID/Revision register value of 0x4110 are affected, as shown in [Table 2](#).

#### Fix

Devices with Date Code 2107 or later are not affected. These devices have a Device ID/Revision value of 0x4111.

## 6. Module: Unimplemented byte on Device Configuration Register

The MCP960X/L0X/RL0X Configuration Register is 8 bits wide followed by an unimplemented byte which outputs 0x00 during sequential Read command. This byte is shown in Table 5-1 "Summary of Registers and Bit Assignment" of Revision G of the data sheet.

### **Work around**

Ignore the byte.

### **Date Codes that pertain to this issue:**

All production devices.

### **Fix**

None.

## 7. Module: Receive Protocol or Repeat Read Command

On some devices of the MCP960X/L0X/RL0X, the Repeat Read command or the receive protocol may not function properly. During Repeat Read command, the device is expected to retain the previously set register pointer and continue to output data from the selected register. However, on some devices, the device may continue to output data from the following register, just as a Sequential Read command.

### **Work around**

Always set the register pointer prior to each Read Command as shown on Figure 4-3 of the data sheet.

### **Date Codes that pertain to this issue:**

- MCP9600/L00/RL00: All production devices before Date Code 2121 and with Device ID/Revision register value of 0x4113 are affected, as shown on [Table 1](#).
- MCP9601/L01/RL01: All production devices before Date Code 2107 and with Device ID/Revision register value of 0x4110 are affected, as shown on [Table 2](#).

# MCP9600/01

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet:

1. The MCP9600/L00/RL00 Input Range Bit of the Status Register (Bit 4) will be clarified (from current description, Revision E Data Sheet DS20005426E) on the next data sheet revision, as described in [Module 3](#).
2. The MCP9601/L01/RL01 Open Circuit detection threshold  $V_{SiOC}$  and  $V_{SiNOR}$  will be clarified (from current description, Revision F Data Sheet DS20005426F) on the next data sheet revision, as described in [Module 5](#).

**TABLE 1: SILICON ISSUE SUMMARY MCP9600/L00/RL00**

Module	Feature	Issue Summary	Affected Device ID/Revision <sup>(1)</sup>				Fixed Date Code
			0x4011	0x4012	0x4013	0x4014	
1	T <sub>H_ACY</sub>	This parameter may not meet data specification starting from Rev C data sheet DS20005426C (MCP9600 only)	X	—	—	—	1723
2	t <sub>STRETCH</sub>	This parameter may not meet data specification (MCP9600/L00/RL00)	X	X	—	—	1845
3	Input Range	Device Characteristics changed from the data sheet description (MCP9600/L00/RL00)	X	X	—	—	1845
4	Extra Byte	Correction to the Device Characteristics (MCP9600/L00/RL00)	X	X	—	—	1845
6	I <sup>2</sup> C Read	Unimplemented byte on Device Configuration Register (MCP9600/L00/RL00) Affected	X	X	X	X	—
7	Receive Protocol	The Repeat Read command or the Receive Protocol may not function properly (MCP9600/L00/RL00) Affected.	X	X	X	—	2121

**Note 1:** The Device ID/Revision Register is found in the user register pointer 0x20.

**TABLE 2: SILICON ISSUE SUMMARY MCP9601/L01/RL01**

Module	Feature	Issue Summary	Affected Device ID/Revision <sup>(1)</sup>		Fixed Date Code
			0x4110	0x4111	
5	Open Circuit Detection	Open Circuit detection mechanism may not correctly assert (MCP9601/L01/RL01)	X	—	2107
6	I <sup>2</sup> C Read	Unimplemented byte on Device Configuration Register (MCP9601/L01/RL01) Affected	X	X	—
7	Receive Protocol	The Repeat Read command or the Receive Protocol may not function properly (MCP9601/L01/RL01).	X	—	2107

**Note 1:** The Device ID/Revision Register is found in the user register pointer 0x20.

## APPENDIX A: DOCUMENT REVISION HISTORY

### Rev. E Document (10/2021)

Updated [Module 7](#), date code for the MCP9600/L00/RL00.

### Rev. D Document (04/2021)

- Added Errata [Module 5](#).
- Added Errata [Module 6](#).
- Added Errata [Module 7](#).
- Updated [Table 1](#) and [Table 2](#).
- Updated minor typographic corrections throughout the document.

### Rev. C Document (5/2019)

- Added Errata Modules 2, 3 and 4.

### Rev. B Document (9/2017)

- Added Fix regarding the devices with Date Code of 1723.
- Added [Note 1](#) to [Table 1](#).

### Rev. A Document (5/2017)

- Initial release of this document.

NOTES:

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

**Trademarks**

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2017-2021, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-8855-2

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4485-5910  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-72400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820